### MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible: yes \_\_\_\_\_ no ×

Property Name: Trinity United Methodist Church	Inventory Number: WO-568
Address: 8339 Newark Road	Historic district: yes X no
City: Newark Zip Code: 21841	County: Worcester
USGS Quadrangle(s): Ninepin Branch	
Property Owner: Trinity United Methodist Church	Tax Account ID Number: 002709
Tax Map Parcel Number(s): 151 Tax Map Number	er: 40
Project: Historic Structures Survey along US-113 Agency	: Maryland SHA
Agency Prepared By: Hardlines Design Company	
Preparer's Name: Roy Hampton	Date Prepared: 9/27/2007
Documentation is presented in: Compliance Report and Historic Context for Prop Mile Branch Road to Massey Branch	posed Highway Improvements-U.S. 113: Five
Preparer's Eligibility Recommendation: Eligibility recommended	X Eligibility not recommended
Criteria: A B C D Considerations: A B	B _ C _ D _ E _ F _ G
Complete if the property is a contributing or non-contributing resource	to a NR district/property:
Name of the District/Property:	
Inventory Number: Eligible: yes	Listed: yes
Site visit by MHT Staff yes X no Name:	Date:
Site visit by MHT Staff yes X no Name:  Description of Property and Justification: (Please attach map and photo)	Date:
Description of Property and Justification: (Please attach map and photo)	
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M	IIHP form.
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M  NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tr	IIHP form. rends other than Methodist religious practice in
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M  NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tr  twentieth century Newark and is recommended as not eligible under Criterion A.	TIHP form.  Tends other than Methodist religious practice in a recommended as not eligible under Criterion B.  Worcester County church, and there are several amples of this style. The building's exterior m. The building does not have sufficient integrity
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tr twentieth century Newark and is recommended as not eligible under Criterion A.  Criterion B: The building is not associated with persons important in history, and is  Criterion C: The building is a fairly typical small-scale Gothic Revival wood-frame similar churches in the surrounding communities that are equally good or better exa integrity has also been compromised by the installation of aluminum siding and trin of design, materials, workmanship, or feeling and and it lacks historical and architecture.	TIHP form.  Tends other than Methodist religious practice in a recommended as not eligible under Criterion B.  Worcester County church, and there are several amples of this style. The building's exterior m. The building does not have sufficient integrity
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tretwentieth century Newark and is recommended as not eligible under Criterion A.  Criterion B: The building is not associated with persons important in history, and is Criterion C: The building is a fairly typical small-scale Gothic Revival wood-frame similar churches in the surrounding communities that are equally good or better exaintegrity has also been compromised by the installation of aluminum siding and trin of design, materials, workmanship, or feeling and and it lacks historical and architecteliable under Criterion C.	TIHP form.  Tends other than Methodist religious practice in a recommended as not eligible under Criterion B.  Worcester County church, and there are several amples of this style. The building's exterior m. The building does not have sufficient integrity
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tr twentieth century Newark and is recommended as not eligible under Criterion A.  Criterion B: The building is not associated with persons important in history, and is Criterion C: The building is a fairly typical small-scale Gothic Revival wood-frame similar churches in the surrounding communities that are equally good or better exa integrity has also been compromised by the installation of aluminum siding and trin of design, materials, workmanship, or feeling and and it lacks historical and architecteligible under Criterion C.  MARYLAND HISTORICAL TRUST REVIEW	TIHP form.  Tends other than Methodist religious practice in a recommended as not eligible under Criterion B.  Worcester County church, and there are several amples of this style. The building's exterior m. The building does not have sufficient integrity
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tr twentieth century Newark and is recommended as not eligible under Criterion A.  Criterion B: The building is not associated with persons important in history, and is Criterion C: The building is a fairly typical small-scale Gothic Revival wood-frame similar churches in the surrounding communities that are equally good or better exaintegrity has also been compromised by the installation of aluminum siding and trin of design, materials, workmanship, or feeling and and it lacks historical and architecelegible under Criterion C.  MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended  Eligibility not recommended	rends other than Methodist religious practice in serecommended as not eligible under Criterion B. Worcester County church, and there are several amples of this style. The building's exterior in. The building does not have sufficient integrity ctural significance. It is recommended not
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tretwentieth century Newark and is recommended as not eligible under Criterion A.  Criterion B: The building is not associated with persons important in history, and is Criterion C: The building is a fairly typical small-scale Gothic Revival wood-frame similar churches in the surrounding communities that are equally good or better exaintegrity has also been compromised by the installation of aluminum siding and trin of design, materials, workmanship, or feeling and and it lacks historical and architecelegible under Criterion C.  MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended  Eligibility not recommended  Criteria:  A  B  C  D  Considerations:  A	rends other than Methodist religious practice in serecommended as not eligible under Criterion B. Worcester County church, and there are several amples of this style. The building's exterior in. The building does not have sufficient integrity ctural significance. It is recommended not
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tretwentieth century Newark and is recommended as not eligible under Criterion A.  Criterion B: The building is not associated with persons important in history, and is Criterion C: The building is a fairly typical small-scale Gothic Revival wood-frame similar churches in the surrounding communities that are equally good or better exaintegrity has also been compromised by the installation of aluminum siding and trin of design, materials, workmanship, or feeling and and it lacks historical and architecelegible under Criterion C.  MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended  Eligibility not recommended  Criteria:  A  B  C  D  Considerations:  A	rends other than Methodist religious practice in serecommended as not eligible under Criterion B. Worcester County church, and there are several amples of this style. The building's exterior in. The building does not have sufficient integrity ctural significance. It is recommended not
Description of Property and Justification: (Please attach map and photo)  The building description and significance statement will be found in the attached M NRHP Recommendation: Not eligible  Criterion A: The church is not associated with any significant historical events or tr twentieth century Newark and is recommended as not eligible under Criterion A.  Criterion B: The building is not associated with persons important in history, and is Criterion C: The building is a fairly typical small-scale Gothic Revival wood-frame similar churches in the surrounding communities that are equally good or better exaintegrity has also been compromised by the installation of aluminum siding and trin of design, materials, workmanship, or feeling and and it lacks historical and architecelegible under Criterion C.  MARYLAND HISTORICAL TRUST REVIEW  Eligibility recommended  Eligibility not recommended  Criteria:  A  B  C  D  Considerations:  A  MHT Comments:	rends other than Methodist religious practice in secommended as not eligible under Criterion B. Worcester County church, and there are several amples of this style. The building's exterior in. The building does not have sufficient integrity ctural significance. It is recommended not  BCDEFGG

NR FI	IGIRII	ITY RE	VIEW	FORM

WO-568

### Trinity United Methodist Church

Page 2	2
--------	---

Criterion D: The building appears to have no potential to reveal any significant historical information and is recommended as not eligible under Criterion D.

MARYLAN	ND HISTO	DRICAL	TRUST	REVI	EW							
Eligibility r	ecommen	ded		Eli	gibility not recommen	ded						
Criteria:	A	B	C	D	Considerations:	Α	В	C	D	E	F	G
MHT Com		er, Offic	e of Pres	servatio	on Services			Date			-	
	Revie	wer, Na	tional Re	egister	Program			Date				

Name of Property: Trinity United Methodist Church

MIHP Number: WO-568
Location: 8339 Newark Road
Town / Vicinity: Newark
Date of Construction: 1911
Access: \_\_ Public \_X Private

The church is a Gothic Revival wood frame building with a gabled nave and transept. The building features pointed arch windows with simple leaded glass, and a small tower with open belfry and a squat pyramidal spire. All trim is covered in aluminum and the wall cladding is wide-lap aluminum siding. The foundation is masonry, and appears to be textured concrete block or possibly cast stone.

Constructed in 1911, the building has minor religious significance as one of only two churches still in operation in Newark. The building is also marginally significant in terms of architecture due to its early-twentieth century design. The church is recommended not eligible for the NRHP. Under Criterion A the church is not associated with any significant historical events or trends other than Methodist religious practice in twentieth century Newark. Under Criterion B the building is not associated with persons important in history. Under Criterion C the building is a fairly typical small-scale Gothic Revival wood-frame Worcester County church, and there are several similar churches in the surrounding communities that are equally good or better examples of this style. The building's exterior material integrity has also been compromised by the installation of aluminum siding and trim. Under Criterion D the building appears to have no potential to reveal any significant historical information.

The Trinity congregation is one of the area's oldest, founded in 1835. The church was originally located at Basket Switch, at a location that is still marked by the Old Trinity Cemetery. The current church building in Newark dates to 1911, according to Maryland real property database records, and this date appears consistent with the style and materials of the building. The Worcester County preservation plan lists eighteen churches dating from the 1900–1930 period, including ten wood frame examples.

#### Inventory No. WO-568

# Maryland Historical Trust Maryland Inventory of Historic Properties Form

historic		02 31 -21 NOES 120			
	Trinity United I	Methodist Church			-
other					
2. Location					
street and number	8339 Newark R	d.		_ r	not for publication
city, town	Newark			_ \	vicinity
county	Worcester				
3. Owner of	Property	(give names and mailing	addresses of all owners)	Ĭ	
name	Trinity United I	Methodist Church			
street and number	PO Box 36			telephone	
city, town	Newark		state MD	zip code 21	841
4. Location	of Legal D	escription			
			Ilber		
- 2 22 2	Snow Hill	Worcester County Courthou		folio tax ID nu	mber 002709
city, town	Show Tim	tax map 40	tax parcel 151	tax ib iiu	111001 002700
Contril	buting Resource i	National Register District			***************************************
Contril Determ Determ Record Histori X Other:	buting Resource in mined Eligible for mined Ineligible for ded by HABS/HAI ic Structure Report Compliance Report	n Local Historic District he National Register/Maryla r the National Register/Mary	land Register	13: Five Mile Branch F	Road to Massey Branch
Contril Deterr Deterr Record Histori X Other:	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI in Structure Report Compliance Report	n Local Historic District he National Register/Maryla r the National Register/Mary ER t or Research Report at MH and Historic context for Proposed	land Register		
Contril Deterr Deterr Recore Histori X Other: Category	buting Resource is mined Eligible for the mined Ineligible for the ded by HABS/HAI is Structure Report Compliance Report Ition  Ownership	n Local Historic District he National Register/Maryla r the National Register/Mary ER t or Research Report at MH and Historic context for Proposed  Current Function	land Register T Highway Improvements-U.S. 1	Resource Co	unt
Contril Deterring Deterring Record Histori X Other: Category district	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI in Structure Report Compliance Report	n Local Historic District he National Register/Maryla r the National Register/Mary ER t or Research Report at MH and Historic context for Proposed	land Register		unt Noncontributing
Contril Determ Determ Recore Histori X Other:  Category district X building(s) structure	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI to Structure Report Compliance Report Ition  Ownership  public	n Local Historic District he National Register/Maryla r the National Register/Maryla r the National Register/Mary ER t or Research Report at MH and Historic context for Proposed  Current Functionagriculturecommerce/tradedefense	Iand Register  T  Highway Improvements-U.S. 1 landscaperecreation/culture _X_religion	Resource Co Contributing	unt  Noncontributing  1 building 0 sites
Category district X building(s) structure site	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI ic Structure Report Compliance Report Compliance Report Ition  Ownership publicpublicprivate	n Local Historic District he National Register/Maryla r the Na	Iand Register  T  Highway Improvements-U.S. 1 landscaperecreation/culture _X_religionsocial	Resource Co Contributing  1 0 0	unt  Noncontributing
Contril Determ Determ Record Histori X Other:  Category district X building(s) structure	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI ic Structure Report Compliance Report Compliance Report Ition  Ownership publicpublicprivate	Local Historic District the National Register/Maryla the National Register/Maryla the National Register/Maryla tor Research Report at MH and Historic context for Proposed  Current Functionagriculturecommerce/tradedefensedomesticeducation	Iand Register  T  Highway Improvements-U.S. 1 landscaperecreation/culture _X_religionsocialtransportation	Resource Co Contributing  1 0 0 0	Noncontributing  1 building 0 sites 0 structure 0 objects
Category district X building(s) structure site	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI ic Structure Report Compliance Report Compliance Report Ition  Ownership publicpublicprivate	Local Historic District the National Register/Maryla the National Register/Maryla the National Register/Maryla tor Research Report at MH and Historic context for Proposed  Current Functionagriculturecommerce/tradedefensedomesticdunerary	Iand Register  T  Highway Improvements-U.S. 1 landscaperecreation/culture _X_religionsocialtransportationwork in progress	Resource Co Contributing  1 0 0	unt  Noncontributing
Category district X building(s) structure site	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI ic Structure Report Compliance Report Compliance Report Ition  Ownership publicpublicprivate	Local Historic District the National Register/Maryla the National Register/Maryla the National Register/Maryla tor Research Report at MH and Historic context for Proposed  Current Functionagriculturecommerce/tradedefensedomesticeducation	Iand Register  T  Highway Improvements-U.S. 1 landscaperecreation/culture _X_religionsocialtransportation	Resource Co Contributing  1 0 0 0 1	Noncontributing  1 building 0 sites 0 structure 0 objects 1 Total
Category district X building(s) structure site	buting Resource in mined Eligible for the mined Ineligible for the mined Ineligible for the ded by HABS/HAI ic Structure Report Compliance Report Compliance Report Ition  Ownership publicpublicprivate	current Function  agriculture  commerce/trade  defense  domestic  education  functory  government	land Register  T  Highway Improvements-U.S. 1 landscaperecreation/culture _X_religionsocialtransportationwork in progressunknown	Resource Co Contributing  1 0 0 1 1 Number of Col	Noncontributing  1 building: 0 sites 0 structure 0 objects

7. Description		Inventory No. WO-568
Condition		
excellent	deteriorated	
X good	ruins	
fair	altered	

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

Trinity United Methodist Church is located in the town of Newark on the north side of Newark Road. The building sits in the middle of a small lot, with a gravel drive leading to a parking lot on the west side of the church. The church's modern graveyard is located north and east of the church building. Nearby are a collection of single-family houses as well as a fire station and park. State of Maryland real estate records indicate that the current church building was constructed in 1911.

Trinity United Methodist Church is a wood frame building with a gabled nave and a gabled transept constructed in the Gothic Revival style. The Gothic Revival style first appeared in the United States in the mid-nineteenth century. The style became extremely popular and was used in a number of building types, but was extremely popular in churches. Characteristics common to the Gothic Revival style which are seen in Trinity Church include pointed arch windows and openings and stained glass.

Trinity Church rests on a masonry foundation that appears to be textured concrete block or possibly cast stone. The building has a moderately pitched, cross-gable roof clad in modern asphalt shingles in a dark gray color. The building was re-clad in white wide lap aluminum siding in the 1950s or 1960s. The aluminum siding is probably covering original horizontal wood siding. The building's original wood trim is also covered in aluminum. A small square tower with a pointed arch belfry opening, wood railing, and a squat pyramidal spire topped with a cross is located at the southeast corner of the building above the main entrance. The tower has a stepped back appearance so that the bottom of the tower is wider than the top. The building features narrow lancet windows with stained glass as well as larger windows composed of three lancet windows next to one another creating a prominent focal point. The main entrance to the church is located in the belfry and is accessed by a set of five brick steps with a metal railing that leads to a small brick landing in front of the front door. The main entrance is composed of a set of double doors. These wood doors have fourteen-panels each and appear to be original to the church. Modern, white metal storm doors have been placed in front of the wood double doors.

A modern front gabled brick parish hall is located northwest of the church. The parish hall features eight-overeight windows, cornice returns, multi-panel double doors as well as a classical entrance surround. Both the church and the parish hall are surrounded by a few decorative foundation plants and a few trees are located near the church entrance. The church sits at a higher grade than the road and a short brick and stone retaining wall separates the church grounds from Newark Road.

8. Signific	cance			Inventory No. WO-568
Period	Areas of Significance	Check and	justify below	
1600-1699 1700-1799 1800-1899 X 1900-1999 2000-	agriculture archeology X architecture art commerce communications community planning conservation	<ul> <li>economics</li> <li>education</li> <li>engineering</li> <li>entertainment/</li> <li>recreation</li> <li>ethnic heritage</li> <li>exploration/</li> <li>settlement</li> </ul>	health/medicine industry invention landscape architecture law literature maritime history military	performing arts philosophy politics/government e X religion science social history transportation other:
Specific dates			Architect/Builder Unl	known
Construction d	lates 1911			
Evaluation for:				
X	_ National Register	X	_Maryland Register	not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

#### Summary of Significance

Constructed in 1911, the building has minor religious significance as one of only two churches still in operation in Newark. The building is also marginally significant in terms of architecture due to its early-twentieth century design.

However, in terms of National Register of Historic Places eligibility the building lacks the significance and integrity necessary for inclusion. The building has lost integrity of materials, workmanship, and feeling. Under Criterion A the church is not associated with any significant historical events or trends other than Methodist religious practice in twentieth century Newark. Under Criterion B the building is not associated with persons important in history. Under Criterion C the building is a fairly typical small-scale Gothic Revival wood-frame Worcester County church, and there are several similar churches in the surrounding communities that are equally good or better examples of this style. The building's exterior material integrity has also been compromised by the installation of aluminum siding and trim. Under Criterion D the building appears to have no potential to reveal any significant historical information.

#### Historic Context

Newark

Newark began as a cluster of development at the crossing of two roads, Newark Road, which once connected the town to Snow Hill and Berlin, and a second road that is now known on the south side of Newark Road as Langmaid Road, and on the north side as Patey Woods Road. The beginnings of a village at the intersection can be traced to the late eighteenth century, with Langmaid Road providing access to commercial landings on Chincoteague Bay. In 1793, the site was part of a land tract known as Yorkshire.<sup>1</sup>

<sup>&</sup>lt;sup>1</sup> Paul B. Touart, Along the Seaboard Side: The Architectural History of Worcester County, Maryland, (Snow Hill: Worcester County Library, 1992), 298.

#### Inventory No. WO-568

## Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Trinity United Methodist Church Continuation Sheet

Number 8 Page 1

It is thought that by 1800, the intersection Newark Road and Langmaid Road probably contained a meeting house, a few dwellings, a blacksmith shop, and a tavern.<sup>2</sup> The earliest map found that names the town is an 1839 anonymous map of Maryland, which labels the settlement as "Newark." The Newark name may have originated from an early name for the town's Methodist Episcopal Church that was named New Ark of the Covenant Church.<sup>3</sup> Another account states that resident A.P. Bowen claimed, in the early twentieth century, that the name had come from a large wood frame building constructed at the town center that was nicknamed "the new ark" because of its resemblance to the biblical Noah's ark.<sup>4</sup>

On an 1877 Lake Griffing atlas, Newark contained one hotel, three retail stores, and three buildings marked G.S. Richardson and Company. Single family residences extended southwest on Newark Road, to the tracks of the Breakwater, Frankford and Worcester Railroad. On Patey Woods Road, single-family house development also extends up to the railroad tracks. The town is shown with about 20 houses, the one-room Schoolhouse No. 3 on Newark Road, and a Methodist Episcopal church. A railroad depot is shown, close to the location of the current 1910-1911 Queponco Station, and a building labeled S.S. Mill was located along the tracks south of the depot building.

Currently, the center of the town features few pre-1900 buildings. This is due to a severe fire in 1905 that destroyed the town's millinery shop, Odd Fellows' Hall, and several houses. In 1918, the Home Bank of Newark was organized, and operated out of a one-room wood frame building, and in 1919, a brick building replaced the previous frame building. Industrial development in twentieth century Newark remained very limited in comparison to development in the Worcester County communities of Snow Hill, Pocomoke City, and Berlin.

Most of the existing single-family houses in Newark today were built from about 1900-1930, according to Maryland Department of Assessments and Taxation records. Construction in the town slowed during the 1930s depression and World War II. In the post-World War II economic expansion of the 1950s and 1960s, several Cape Cod, Minimal Traditional, and Ranch style houses were built on vacant lots in the developed section of Newark, or on the town's outer fringes.

<sup>&</sup>lt;sup>2</sup> Ibid.

<sup>&</sup>lt;sup>3</sup> Ibid.

<sup>&</sup>lt;sup>4</sup> Reginald Truitt and Millard Les Callette, *Worcester County, Maryland's Arcadia* (Snow Hill, Maryland: Worcester County Historical Society, 1977), 96.

<sup>&</sup>lt;sup>5</sup> Ibid, 96.

<sup>&</sup>lt;sup>6</sup> Board of Education of Worcester County. Worcester County: Past and Present, part VII, Communities of Worcester County, (Worcester County Board of Education: 1956), 26-27.

<sup>&</sup>lt;sup>7</sup> Truitt and Les Callette, Worcester County, Maryland's Arcadia, 96.

<sup>8</sup> Ibid, 339.

#### Inventory No. WO-568

## Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Trinity United Methodist Church Continuation Sheet

Number 8 Page 2

In 1956, work began on a bypass road that took US 113 around the south side of Newark, and routed highway traffic away from Newark's central intersection. Today, Newark is mostly residential, with the post office and Mercantile Peninsula Bank buildings being the main non-residential buildings at the town center. Newark also features an RV sales and repair business and a lumber firm, located near the railroad tracks on Patey Woods Road.

Trinity United Methodist Church: 8339 Newark Road

Maryland was originally founded in 1632 by Lord Baltimore as a safe haven for Catholics, but in 1649, shortly after its founding, the Maryland Toleration Act was issued which allowed freedom of worship for all Christians in Maryland. This religious toleration resulted in a variety of people with different religious backgrounds settling in Maryland. One of the religions that took a foothold in Maryland was Methodism. Methodism began in 1729 by a group of University of Oxford students. The movement was brought to the United States by English and Irish emigrants, and the earliest societies were formed in 1766 in New York City, Philadelphia and Pipe Creek, Maryland. The American Methodist church was first established in 1771, and later was formally organized in 1784 at a Baltimore, Maryland conference.<sup>10</sup>

Founded in 1835, the Trinity Methodist Church congregation is one of the oldest in the area. However, the current church building located in Newark was not the congregation's first church building. The original Trinity church was located in present day Basket Switch a short distance southwest of Newark. The first Trinity Church appears on an 1866 map of the area. Most of the churches labeled on this Worcester County map are Methodist churches suggesting Methodism was the predominant religion in the area at the time. The church continues to appear on an 1877 atlas in Basket Switch. In 1911, the current Trinity Church in Newark was constructed on the west side of town along Newark Road. Today the congregation is currently managed along with the nearby Bowen United Methodist Church, under a single pastor. It is not known if the original church in Basket Switch was destroyed by fire or if it was simply abandoned in favor of the Newark location. Today there are no remnants of the church building in Basket Switch. Old Trinity Cemetery remains at the location and a depression in the ground may indicate the previous site of the church.

The architectural style and form of the current 1911 Trinity United Methodist Church appears to have been typical of church architecture in Worcester County in the early twentieth century. Other cross-gable wood frame

Wikipedia, "History of Maryland." http://wikipedia.org/wiki/History\_of\_Maryland#Early\_European\_exploration (accessed June 28, 2007).
 John H. Ness, "History of Methodism", http://www.sppauljax.org/history of methodism.htm (accessed June 28, 2007).

# Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. WO-568

Name Trinity United Methodist Church Continuation Sheet

Number 8 Page 3

churches with entrance belfries appear in Showell, Germantown, Campbelltown, Pocomoke City, and Snow Hill. Given the large number of these churches still in existence Trinity United Methodist Church is a common church type and there are other examples with better integrity in the surrounding area.

<sup>11</sup> Touart, Along the Seaboard Side, 322, 324, 375, and 420.

### 9. Major Bibliographical References

Inventory No. WO-568

Board of Education of Worcester County. Worcester County: Past and Present, part VII, Communities of Worcester County. 1956, on file at Worcester County Room, Snow Hill Public Library.

Lewis, J. Frank. The Maryland Directory. Baltimore: J. Frank Lewis and Company, 1878.

Ness, John H. "History of Methodism." http://www.sppauljax.org/history of methodism.htm. (Accessed June 28, 2007).

Touart, Paul B. Along the Seaboard Side: The Architectural History of Worcester County, Maryland. Snow Hill: Worcester County Library, 1992.

10.	Geogr	aphical	Data
-----	-------	---------	------

Acreage of surveyed property _	1 acre	_	
Acreage of historical setting _	1 acre	_	
Quadrangle name	Ninepin Branch	Quadrangle scale:	1:24,000

#### Verbal boundary description and justification

Trinity United Methodist Church is bounded by parcel 151, map 40 of Worcester County. The current boundary and the historical boundary for the property are identical as the property boundaries for the church have not changed. The boundary is large enough to encompases the entire church building and corresponds to the historical boundary of the property. See attached parcel map.

### 11. Form Prepared by

name/title	Roy Hampton, Senior Architectural Historian and Heather Kenney, Architectural				
organization	Hardlines Design Company	date	06/08/2007		
street & number	4608 Indianola Ave.	telephone	614-784-8733		
city or town	Columbus	state	ОН		

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Maryland Department of Planning 100 Community Place Crownsville, MD 21032-2023 410-514-7600

# Maryland Historical Trust Maryland Inventory of Historic Properties Form


Inventory No. WO-568

Name Trinity United Methodist Church Continuation Sheet

Number 9 Page 1

Truitt, Reginald and Millard Les Callette. *Worcester County, Maryland's Arcadia*. Snow Hill, Maryland: Worcester County Historical Society, 1977.

Wikipedia. "History of Maryland." http://wikipedia.org/wiki/History\_of\_Maryland#Early\_European\_exploration. (Accessed June 28, 2007).



WO-568, Trinity United Methodist Church, Newark, Worcester County, Resource Sketch Map-Tax Map 40, Parcel 151



WO-568 Trinity United Methodist Church, Newark, Worcester County, Ninepin Branch Quad



Inventory No. WO-568
Trinity United Methodist Church
Worcester County. Maryland
Heather Menney
May 29, 2007
MO SHPO
Southeast corner of building looking northwest.
#1 of 2



Inventory No. 568
Trinity United Methodist Church
Worcester County, Maryland
Heather Kenney
May 29, 2007
MD SHPO
Southwest Corner of building looking northeast.
#2 of 2